BOMBARDIERToronto Site

PROPRIETARY INFORMATION

PPS Revision Notice

As of February 12, 2016, the following PPS's have been released, having been revised as noted below:

PPS 13.27, Issue 7 – Trimming and Repair of Insulation Blankets

- Revised tape to be used for trimming and repair of insulation blankets to specify use of polyether ether ketone (PEEK) tape, reinforced, pressure sensitive, to DSC 91-23 (opaque white) or DSC 91-26 (dull white).
- Added to the Safety Precautions section a statement regarding the safety precautions in general, explaining that the safety precautions specified are specific to Bombardier (Toronto Site) to meet Canadian Federal and Provincial government environmental, health and safety regulations and that suppliers, subcontractors and partners are responsible for ensuring that their own environmental, health and safety precautions satisfy the appropriate local government regulations. Note: This paragraph is taken, with a little modification, from PPS 13.26 (para. 3.6) and has been added to this PPS to highlight this provision.
- Revised personnel requirements to specify personnel must have a good working knowledge of the applicable procedure and requirements as specified and must have exhibited their competency to their supervisor.

This revision notice lists brief summaries of technical changes introduced for each of the revised PPS's. Please note that these summaries are not detailed and are intended only to assist in alerting PPS users to changes which may affect them; refer to the applicable PPS for authorized, detailed procedure and requirements.

Notice #2016-008 Page 1 of 1