

As of May 10, 2016, the following PPS's have been released, having been revised as noted below:

PPS 9.22, Issue 26 – Assembly of Connectors

- Clarified section regarding placement of connector identification sleeves and cable markers to specify that for wire bundles within conduit or an overbraid shield to apply the connector identification sleeves or cable markers over the conduit or overbraid shield.
 - Added to the Safety Precautions section a statement regarding the safety precautions in general, explaining that the safety precautions specified are specific to Bombardier (Toronto Site) to meet Canadian Federal and Provincial government environmental, health and safety regulations and that suppliers, subcontractors and partners are responsible for ensuring that their own environmental, health and safety precautions satisfy the appropriate local government regulations. Note: This paragraph is taken, with a little modification, from PPS 13.26 (para. 3.6) and has been added to this PPS to highlight this provision.
-

This revision notice lists brief summaries of technical changes introduced for each of the revised PPS's. Please note that these summaries are not detailed and are intended only to assist in alerting PPS users to changes which may affect them; refer to the applicable PPS for authorized, detailed procedure and requirements.
