BOMBARDIER

Toronto Site

PROPRIETARY INFORMATION

PPS Revision Notice

As of November 18, 2016, the following PPS's have been released, having been revised as noted below:

PPS 10.24, Issue 15 - Preparation of Honeycomb Cores for Lay-Up in Sandwich Panel Assemblies

- Updated manufacturer's company name for L-501-8800 flyscreen from J. D. Lincoln to Cytec Industries Inc.
- Added new option of Axiom Materials Inc. AX-3114FR-8800 flyscreen to DHMS P1.48.
- Clarified that during lay-up, the resin rich side of the flyscreen should be facing the core.

PPS 30.27, Issue 4 - Annealing Copper Tubing

- Updated overall PPS format.
- As this process is no longer being performed at Bombardier Toronto site, hence, specified that safety precautions applicable to the materials and procedures specified herein shall be defined by the subcontractor performing the work for Bombardier Toronto.
- Revised Personnel Requirements wording.

This revision notice lists brief summaries of technical changes introduced for each of the revised PPS's. Please note that these summaries are not detailed and are intended only to assist in alerting PPS users to changes which may affect them; refer to the applicable PPS for authorized, detailed procedure and requirements.

Notice #2016-045 Page 1 of 1