

As of November 23, 2016, the following PPS's have been released, having been revised as noted below:

**PPS 13.27, Issue 8 – Trimming and Repair of Insulation Blankets**

- Added DSC 91-21 flame retardant, pressure sensitive, Tedlar tape as an acceptable alternative to DSC 91-23 and DSC 91-26 polyether ether ketone (PEEK) tapes for trimming and repair of insulation blankets. These tapes are now collectively referred to as insulation tapes.
  - Added Celsius equivalents to temperatures expressed in Fahrenheit degrees.
- 

---

This revision notice lists brief summaries of technical changes introduced for each of the revised PPS's. Please note that these summaries are not detailed and are intended only to assist in alerting PPS users to changes which may affect them; refer to the applicable PPS for authorized, detailed procedure and requirements.

---