




DRILL "D" THRU



Ⓐ DETAIL -2



DRILL $\frac{3}{32}$ " (0.094)
1 HOLE



DRILL "D" THRU TO MEET
 $\frac{3}{32}$ " DIA HOLE

DRILL "B" DIA. TO DEPTH "A"

DETAIL -1

PART NO.	DESCRIPTION	MATERIAL	DIM. 'A'	DIA. 'B'	DRILL 'D'
Ⓑ -3	PLUG-TRANS. VENT.	AN814-9D	—	—	0.063
Ⓐ -2	PLUG-TRANS. VENT.	AN814-4DL	—	—	0.063
CANCEL -1	PLUG-TRANS. VENT.	AN806-4D	0.53	0.172	0.063

DRAWN	FL. GUAGIER	CLASSIFICATION	STANDARD
CHECKED	<i>[Signature]</i>	PLUG -	CSP-105
STRESSED	<i>[Signature]</i> 10/5/58	TRANSMITTER VENT	
APPROVED			

FMG 71867

Ⓑ ADDED -3 28-7-66
Ⓐ REVISED 28-10-58